



Bräuniger IQ Motor eco / IQ Motor eco GPS

Firmware release notes

V1.4.02 (2017-08-09)

New menu setting for RPM factor: Menu – FL Motor 2 – RPM factor: 0.5 / 1 / 2

The RPM number received from the FL Motor 2 data transmitter is multiplied with this factor. This is necessary for 4-stroke and multi-cylinder 2-stroke engines.